




1




Presser avant insérer
Press before insert



2




Glisser dessous la pédale
Slide under foot control




visuels non contractuels


3



Glisser par dessus le pressoir
Slide over the arm control



4



Press'n Clean Connect

260 rue des Barronières
01700 Beynost France
Tél : 04 72 01 50 60
Fax : 04 78 88 39 01

Actiwork
BIEN VIVRE SON TRAVAIL

Option PMR borne 5L CS76A001AY_000_000

This document is the proprietary property of Actiwork. Its use is authorized only for responding to a request for quotation, or for the performance of work for Actiwork. All questions must be referred to Actiwork.
Ce document est propriété de Actiwork, son utilisation n'est autorisée que pour répondre à une demande de chiffrage, ou pour effectuer un travail pour Actiwork. Toute question est à adresser à Actiwork.